

1. If more than six stabilizers are thermally damaged thru warpage, deformation or deterioration, or plug with ash or slag, such that they fail to perform their intended function within one year of installation in burners set, operated and maintained to RJM requirements.

2. If Unit 2 fails to meet any of the performance conditions as outlined in Article 2.7 and as determined during the post-installation testing as per Article 2.8.

3.3 The stabilizers shall be delivered to the Intermountain Power Project site by no later than October 21, 1991.